



SKEP III Home Office Support Site Visit Report

**WAHIB
MEDANAT**
consultant engineers

Consultant	Wahib Medanat Consultant Engineer	Rep No.	23-27032022
Contractor	Dijlah Establishment Constr. Contracting	Tender No.	(11/2019/USAID/SKEP/3/S) Schools for a Knowledge Economy Project (SKEP) - Phase (3) Package (1, 2)
Site Name	Jumana Bint Abit Taleb Basic Mixed School - Jerash	Day/ Date	Sun. 27/03/2022
Duration of Project	450 Calendar Days	Total Project Budget	8,314,983.735 JD

No.	Visitors		Remarks
1	Suhair Amarin	- Project Dir./Head of Architectural Department	
2	Wahib Medanat	- General Manager	
2	Hashem Abu Kwaik	- Senior Civil Engineer	
3	Akram Khammes	- Head of Electrical Department	
4	Marwan Sonna'a	- Head of Mechanical Department	
5	Hasan Shaqboua	- Quality Control Manager	

Visit Notes

No.	Description
1	The team observed that the built stones at the entrance still not rectified by Contractor as required.
2	The team inspected the installation of the aluminum flashing for the roof insulation and stressed on the Contractor to fill the mastic under the flashing correctly.
3	The team observed the unacceptable status of granite cladding for the staircases and stressed on the Contractor to rectify all defected parts due to wrong cutting of granite pieces.



No.	Description
4	The supervision team observed that in number of windows, the aluminum sections do not match the actual dimensions of the opening. Therefore, those sections should be replaced.
5	The team inspected the executed porcelain floor tiles and stressed on the Contractor to replace any teething cases.
6	The team inspected the built block above false ceiling at the wet area in the multi-purpose hall and stressed on the Contractor to fill all gaps between blocks before installing the suspended ceiling.
7	The team inspected the electro-mechanical installation work under the ceilings.
8	The team inspected the ceramic tiling work for the walls at the wet area.
9	The team Inspected the executed granite for staircase parapets.



Project ID
Sign on Site





Sterilization and signing visitors' attendance sheet at the entrance of the site, complying with Covid-19 Protocol





General view of the project site
(figures: 01, 02, 03 & 04)

(Figure: 01)



(Figure: 02)



(Figure: 03)



(Figure: 04)



The team observed that the built stones at the entrance still not rectified by Contractor as required

(Figure: 05)



The team inspected the installation of the aluminum flashing for the roof insulation and stressed on the Contractor to fill the mastic under the flashing correctly

(Figure: 06 & 07)

(Figure: 06)



(Figure: 07)



The team observed wrong cutting of granite pieces at the staircases and stressed on the Contractor to rectify all defects

(Figure: 08 & 09)

(Figure: 08)



(Figure: 09)



The team inspected the executed granite for staircase parapets


(Figure: 10)



(Figure: 11)

The team inspected the executed porcelain floor tiles and stressed on the Contractor to replace any teething cases

(Figure: 11 & 12)



(Figure: 12)



(Figure: 13)

The team inspected the built block above false ceiling at the wet area in the multi-purpose hall and stressed on the Contractor to fill all gaps between blocks before installing the suspended ceiling



(Figure: 13 & 14)

(Figure: 14)



The team inspected the ceramic tiling work for the walls at the wet area

(Figure: 15)



The supervision team observed that in number of windows, the aluminum sections do not match the actual dimensions of the opening. Therefore, those sections should be replaced

(Figure: 16)



(Figure: 17)

The team inspected the electro-mechanical installation work under the ceilings



(Figure: 17 & 18)

(Figure: 18)