

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name Hay Al Iskan Basic mixed - Jerash
Package Package 2
Contractor Dijlah Est. Construction Co.
Tender No. 10/2019/USAID/SKEP/3/2

Rep No. QC-21 11
Date 9 / 08 / 2021

Description of Non Conformance	Corrective Action	Required by / When
1.Minor defect in the verticality of one column. 2. Prominence in one of the internal walls in the first floor-staircase entrance was observed. 3. Delivering to the site none-complying stones.	1. Repair can be done at the plastering stage. 2. Casting a concrete strip to cancel the prominence. 3. Removing the un-complied stones outside the site and avoid delivering similar defected stones.	The Contractor/Immediately
<p align="center">Report Prepared by</p>	Hassan Shaqbua, Supervision Quality Control Manager	
<p align="center">Contractor's Response</p>		
Immediate response by Contractor.		
<p align="center">Notes</p>		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report

Before Photos



Prominence Repair

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report

Photos After:



Prominence Repair

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Removing Un- Complied Stones Outside the Site

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature