



School for Knowledge

Economy Project (SKEP) Phase III – Package 2

Defects Liability Period/ General Observations

Periodic Site Visits/ January 16, 2023

Thahr Al Sarow Basic School for Boys





- +962 6 5817847
- +962 79 7650576
- fax +962 6 5862357
- mail@medanat.com info@medanat.com





AUSTRIA HELLAS No.: 20152200003939 Monagement System on po 15O 45001 : 2018

Management System as per EN ISO 9001 : 2015



| Table of Contents

	Page
Table of Contents	2
l Project Particulars	3
1.1 Contract Main Information	3
2 Periodic Site Visit	5
3 Website Reports Links	12
3.1 Daily Reports	12
3.2 Weekly Reports	12
3.3 Monthly Reports	12
3.4 CMTO Inspection Reports	12
3.5 Quality Reports	12



1 | Project Particulars

1.1 Contract Main Information

Contract Name:	School for Knowledge Economy Project (SKEP) Phase III – Package (2)					
Owner:	Ministry of Education (MOE)					
Employer:	Ministry of Public Works & Housing (MPWH)					
Funded By:	United States Agency for International Development (USAID)					
Consultant:	Wahib Medanat Consultant Engineers					
Project Management:	Trigon Associates (CMTO)					
Contractor:	Dijlah Establishment Constr. Contracting					
Contract No.:	10/2019/USAID/SKEP/3/2					
Commencement Date:	21/10/2020					
Time for Substantial Completion of the Work:	Thahr Al-Sarow Basic School for Boys- Jerash: 450 Days					
	Jumana Bint Abi-Taleb Basic Mixed School-Amman: 450 Days					
	Hay Al Iskan Basic Mixed School – Jerash : 450 Days					
Time to Complete the Work Including Punch List Items:	Within 14 Calendar days for each School from the date of taking over committee inspection					
Contract Amount at Award:	8,314,983.735 JOD					



Amount of Liquidated Damages:	Thahr Al Sarow Basic School for Boys- Jerash: 2000 JOD/ Day but not to exceed 15% of total amount for the School
	Jumana Bint Abi Taleb Basic Mixed School Amman: 200 JOD/ Day but not to exceed 15% of total amount for the School
	Hay Al Iskan Basic Mixed School- Jerash: 2000 JOD/ Day but not to exceed 15% of the total amount for the School
Defects Liability Period:	(730) Calendar Days for all Civil & Electromechanical works from the date of Substantial Completion for each school including the maintenance of plantation works
Maintenance Guarantee for Defects Liability Period:	5% of the final Contract Sum
Percentage of Retention from Interim Payment Certificate:	10% of each payment
Limit of Retention Money:	5% of Contract Sum as amended
Period of Time for Payment to be made after Certification by the Engineer:	60 Calendar Days
Minimum Amount of Interim Payment Certificate:	JOD 300,000 (Three hundred thousand Jordanian Dinar) for all schools under the Package
Payment for Imported Materials	40% upon receipt of approved bill of lading and another 20% when stored on site to the Engineer's approval
Payment for Local Materials and Equipment	60% and restricted to cement and reinforcin steel when stored on site to the Engineer's approval.



NAHIB MEDANAT	USAID	SKEP III Defec	t Liability F	Period Site Visit		
	Consultant	Wahib Medanat Consultant Engineer	Rep No.	22-16012023 (11/2019/USAID/SKEP/3/S) Schools for a Knowledge Economy Project (SKEP) - Phase (3) Package (1, 2)		
	Contractor	Dijlah Establishment Constr. Contracting	Tender No.			
	Site Name	Thahr Al Sarow Basic School for Boys- Jerash	Day/ Date	Mon. 16/01/2023		
No.	Visitors (Engi	neer)		Remarks		
1	Eng. Suha	x Amerin		===		
2	Eng. Marwa			M		
	Eng. Akraw			#1		
4	-	Abu Quante		\$35 B		
No.	Visitors (Con	tractor)		Remarks		
1	4.6/0	Line	-	25		
2						
3						
No.	Owner Repre	esentative		Remarks		
1	العفنن	V Eliv		5		
2						
3		100				



EUSAIC Schools for Knowledge Economy Project SKEP III Defect Liability Period Site Visit Report Consultant Wahib Medanat Consultant Engineers 22-16012023 Thahr Al Sarow Basic School for Boys - Jerash Date 16/1/2023 Site Name Package Package 2 Dijlah Establishment Constr. Contracting Contractor 10/2019/USAID/SKEP/3/2 Tender No. No. Function Defect Action Taken Status Photo Floor Comments 1 Ground Floor School main entrance door One of the main school door's hinges is broken and needs replacement 2 Ground Floor Some hose bibs (bidets) are missing



_			ı		
		Main Staircase	A broken granite at the landing shall be replaced		
4	Ground Floor	Corridor	Water leakage was observed in one of the fire hose cabinets		
5	All Floors	General	Some water coolers do not work		



6		General	Leakage, corrosion and other defects were observed in some radiators		
7	All Floors	Toilets	Some floor drains do not have covers		
8	All Floors	General	Overall cleaning is required		
9	All Floors	General	The elevator needs maintenance		



10 First Floor	Kitchen	A broken electrical socket shall be replaced		
11 First Floor	Toilet	Corrosion can be observed on the floor drain cover		
12 First Floor	Toilet	The motion detector needs maintenance		
13 Second Floor	Chemistry Lab	Fume hood works shall be completed		



_					
14	Third Floor	Toilet	A flush button needs maintenance		
			Handrails painting work is unfinished		
16	External Works/Site	Parking Area	A broken marble sill shall be replaced		



_		_			
	External Works/Site	Playground and main entrance steps	Defects in painting		
18	External Works/Site	Site	Lightning poles bolts need to be covered with protection caps		



3 | Website Reports Links

- 3.1 Daily Reports
- 3.2 Weekly Reports
- 3.3 Monthly Reports
- 3.4 CMTO Inspection Reports
- 3.5 Quality Reports